

Basic Vehicle Condition Guide

Report ID: 18,609,315


Version: 2

Created: 19 Dec 2018

Make: Model: XF Jaguar **Body Style:** Sedan Year: 2011 Registration: FZU540 Reg Expiry: 11 Aug 2019 **WoF Expiry: Odometer: Good No:** 15 Nov 2019 103,052 Kms 18609315 VIN: **Next Service:** SAJAC0546BNS19804 107500 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Brian Hill Inspected by:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			-
CV joints			~
Wheel bearings	1		ļ -
Brakes			
Performance	V		I
Hand Brake	•		
Tyres (lowest observed tread	l denth	of tyre)
Left front		7	mm
Right front		, 7	mm
Left rear			mm
		7	-
Right rear	7		mm
Spare Suspension		Yes	
Suspension performance	.,		
Steering performance			
Shock absorbers	•		
	V		
Air Conditioning / Heater	_		
Operation	•		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		
	R		

Signature: