

Report ID: 18,609,468 Version: 1 23 Oct 2018 Created:

Make:	-	Madal	167	Dody Carles		<u>ا</u>	Daaa	E-:I	
	Toyota	Model:	IST	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	HRM587	Reg Expiry:	01 Nov 2018	Engine			<u> </u>
WoF Expiry:	18 Oct 2019	Odometer:	88,879 Kms	Good No:	18609468	Oil level	~		
VIN:	7AT0H647X14137898	Next Service:		Service Histor	V: No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
	a guide only. Consid					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
			-		-	Coolant condition	~		<u> </u>
Key:		\sim	S PT SC PT S			Performance	~		
S = scratch		\sim (O)		<u>5(0)</u>		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust SPT SC PR						Operation	~		
PT = paint def	ect N	1				Noise	~		
C = crack					PT SC	Clutch			~
P = pin dent	S PT SC			-	241 <u>14</u>	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
. Jiginitan	S SC	C	PT P SC SC	W	SC	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
Clearcoat is coming off vehicle. Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			es)
Only RF window working off RF switch. Holes in trim on inside of door on RF mirror.					Left front	4 n		mm	
						Right front	4	1	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine cov	er and fusebox cover pa	ainted. Surface ru	ist on bare steel par	ts in engine bay. Re	ar muffler not	Suspension performance	~		
original. We	ear on rear suspension b	oushes. Surface r	ust in places under	floor. Corrosion on r	ear discs.	Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats Average						Head lights			
50005						Tail lights	~		
Carpets	Average					Indicators	~		
Danala	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL			
							~		
General (<u>Comments</u>					Window winder FR	~		
Drives ok.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		ļ
Enging Ti	ming Machanisma					Remote locking	~		<u> </u>
•	ming Mechanism:	Timing (K		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte						Date: 23 Oct 20	10		
inspecte	d by: Roger King					Date: 23 Oct 20	10		

I have read and understood this condition guide.

Name:

Signature: