

Report ID: 18,609,679 Version: 1 29 Oct 2018 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JJD485	Reg Expiry:	31 Dec 2018	Engine			L
l	11 Sep 2019	Odometer:	160,464 Kms	Good No:	18609679	Oil level	~		
VIN:	MMU148FK0FH62489	Next Service:	169,000kms	Service History		Smoke & fumes	· ·		
						Performance	· ·		
	port is not a warranty		C 1 1	D		Noise	· ·		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has been	n driven up to 50km/h	from cold. The	/endor recommends	Cooling System	•		
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	· ·		
Key:	sc	-0	SW SP	-M-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc			The	SW	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack				+	S R SC	Clutch	•		~
P = pin dent	HIC				세비	CV joints	~		•
* = decals	sc 916			The	EL SPW	Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S SC S SP SP SC SP SC						Performance 🖌			
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	-	oftvre	
Large stone chip on bottom corner of right front A pillar. Stone chips in windscreen. Right side of rear bumper has been pushed in against right rear guard. Scratches on right rear tail light lens. Crack in right rear									mm
mud flap.						Right front		.o .4	
						Left rear		.4 .2	mm
Condition	oc During Pody Inc	naction				Right rear			
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	pads wearing low.	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	• •		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Good Good						Head lights			
Jeats						Tail lights	•	~	
Carpets	Good					Indicators	~	•	
Panels	Good					Dashboard warning lights	· ·		
Fallels						Wipers (front & rear)	• •		
Dashboa	rd Good					Window winder FL	• •		
						Window winder FR	• •		
General Comments						Window winder RL	~		
						Window winder RR	• •		
						Rear view mirrors	· ·		
						Radio (basic test only)	v v		
						CD (basic test only)	• •		
						Number of keys	2		
						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
									•
Inspected by: Jason Young Date: 23 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: