

Basic Vehicle Condition Guide

Report ID: 52,273


Version: 1

Created: 08 Nov 2018

Make: Model: Nissan Teana **Body Style:** Sedan Year: 2006 Registration: JAQ251 Reg Expiry: 18 Sep 2019 WoF Expiry: **Odometer: Good No:** 20 Nov 2019 51,103 Kms 18610814 VIN: 7AT0DH71X15202825 **Next Service:** Just Serviced **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Scott Date: 06 Nov 2018

Name:

		1	
	Pass	Fail	N/A
Engine		ı	1
Oil level	×		
Smoke & fumes	×		
Performance	×		
Noise	×		
Cooling System		1	
Coolant condition	×		
Performance	×		
Radiator / Hoses (visual)	×		
Transmission		1	
Operation	×		
Noise	×		
Clutch			×
CV joints	×		
Wheel bearings	×		
Brakes			
Performance	×		
Hand Brake	×		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front		7	mm
Left rear	5.0		mm
Right rear	5.0		mm
Spare		Yes	
Suspension			
Suspension performance	×		
Steering performance	×		
Shock absorbers	×		
Air Conditioning / Heater			
Operation	×		
Electrical / Accessories			_
Head lights	×		
Tail lights	×		
Indicators	×		
Dashboard warning lights	×		
Wipers (front & rear)	×		
Window winder FL	×		
Window winder FR	×		
Window winder RL	×		
Window winder RR	×		
Rear view mirrors	×		
Radio (basic test only)	×		
CD (basic test only)	×		
Number of keys	1	-	-
Central locking	×		
Remote locking	×		
Sat. Nav. (basic test only)			×
Reversing camera	×		

Signature: