


Make:	Mazda	Model:	CX-7	Body Style:	SUV
Year:	2008	Registration:	HTF373	Reg Expiry:	13 Nov 2018
WoF Expiry:	20 Nov 2019	Odometer:	107,137 Kms	Good No:	18614374
VIN:	7AT0C13PX14106164	Next Service:	116,000kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs


Body Inspection Comments

Right wing mirror damage

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments
Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✗		
Smoke & fumes	✗		
Performance	✗		
Noise	✗		
Cooling System			
Coolant condition	✗		
Performance	✗		
Radiator / Hoses (visual)	✗		
Transmission			
Operation	✗		
Noise	✗		
Clutch			✗
CV joints	✗		
Wheel bearings	✗		
Brakes			
Performance	✗		
Hand Brake	✗		
Tyres (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	5.5	mm	
Left rear	2	mm	
Right rear	3	mm	
Spare	Yes		
Suspension			
Suspension performance	✗		
Steering performance	✗		
Shock absorbers	✗		
Air Conditioning / Heater			
Operation	✗		
Electrical / Accessories			
Head lights	✗		
Tail lights	✗		
Indicators	✗		
Dashboard warning lights	✗		
Wipers (front & rear)	✗		
Window winder FL	✗		
Window winder FR	✗		
Window winder RL	✗		
Window winder RR	✗		
Rear view mirrors	✗		
Radio (basic test only)	✗		
CD (basic test only)	✗		
Number of keys	1		
Central locking	✗		
Remote locking	✗		
Sat. Nav. (basic test only)			✗
Reversing camera	✗		

Inspected by: Ca Thach

Date: 08 Nov 2018

I have read and understood this condition guide.

Name:

Signature: