

Report ID: 18,615,176 Version: 1 21 Nov 2018 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2006	Registration:	DMA397	Reg Expiry:	03 Apr 2019	Engine			
WoF Expiry:	06 Nov 2019	Odometer:	251,229 Kms	Good No:	18615176	Oil level	~		
VIN:	VSKCVND40A0117274	Next Service:	262000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	S SC S SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ssc dl			The	EID D	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	R SC	Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals	SPSC 91			AL-	BIR SDSC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D SC SC SC SC									
		Notor con	ne defects & blemishes			Performance	~		
Body Insp	pection Comments	Note: son	re delects & blemisnes	may not be disp	blayed in the diagram	Hand Brake		<u> </u>	
Minor spider rust on the roof ,LR tail light broken ,					Tyres (lowest observed tread depth of tyres)				
						Left front		7	mm
						Right front		7	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Wet						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories	-		
Seats	drivers sea	it ripped ,				Head lights	~		
Compete	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	screw hole	es dash ,				Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Donovan Matara Date: 21 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: