

Report ID: 18,615,195 Version: 1 Created: 31 Oct 2018

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JLE788	Reg Expiry:	03 Feb 2019	Engine	1	I	1
WoF Expiry:		Odometer:	50,596 Kms	Good No:	18615195	Oil level	~		
VIN:	MM0DJ2HAA0W1467	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition	~		
						Performance	~		
Key:	SC	-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent	sc			The	Ell s	Operation	~		
R = rust PT = paint defe				$\int$	JHH	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	sc 916			The	ELIPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	e defects & blemisbes	may not be disc		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	) )
Rear tyres edge worn.					Tyres (lowest observed tread depth of tyres)   Left front 4 0				
								.0	mm
						Right front Left rear		.0	mm
								.0	mm
Conditions During Body Inspection: Wet						Right rear 2.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meenspeede	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
								1	
Inspected by: Scott Willoughby Date: 30 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....