

Report ID: 18,617,979


Version:

Created: 30 Oct 2018

	Make:	Toyota	Model:	Hilux	Body Style:	Utility
ı	Year:	2011	Registration:	FYE583	Reg Expiry:	22 Feb 2019
ı	WoF Expiry:	13 Jun 2019	Odometer:	241,127 Kms	Good No:	18617979
ı	VIN:	MR0FZ22G901047707	Next Service:	248000	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Screw holes in dash. Stone chips front screen. Taillights cracked. Tuff deck is worn. Dent right rear cab corner. Drivers door rubber torn. Dent right A pillar

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Poor			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Name:

Pass	Fail	N/A
>		
~		
~		
~		
	ı	
>		
~		
~		
~		
~		
		~
~		
~		
'		
~		
l depth	of tyre	es)
8	3	mm
1	0	mm
9	9	mm
1	0	mm
	Yes	
	1	
~		
✓ ✓		
\(\times \)		
<i>y y</i>		
<i>y y y</i>		
\(\times \)		
\(\times \)		
<i>v</i>		
<i>v</i>		
<i>v</i>		
V V V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
	ソ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Reversing camera

Signature:

30 Oct 2018 Inspected by: Brian Hill