

Report ID: 18,618,075 Version: 1 Created: 30 Oct 2018

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	EGC342	Reg Expiry:	04 Sep 2019	Engine	1	I	1
WoF Expiry:		Odometer:	94,528 Kms	Good No:	18618075	Oil level	~		
VIN:	KMHBT51DR8U76161	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
			·			Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and tl	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	S D PT * S PT	-161-	S D	Radiator / Hoses (visual)	~		+
S = scratch						Transmission	•		
D = dent	s dik			1n-	HID *W	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs W S PT * S D PT S S D						Performance V			
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	oftur))
Headlights dull Aerial missing						Left front			
Head unit need codes							3.5 mm		-
						Right front		.5	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	<u>ince inspectic</u>	<u>in comments</u>			Suspension		1	
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories	1	1	
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	ard Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments Engine noisy and excessive vibration during test drive						Window winder RL	~		
Engine nois	sy and excessive vibratio	on during test dr	ve			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 90	,000	Reversing camera			~
Inspected by: Ca Thach Date: 30 Oct 2018									
Inspected by: Califiach Date: 30 Oct 2018									
I have read and understood this condition guide. Name:									