


Make:	Toyota	Model:	Celica	Body Style:	Hatchback
Year:	2002	Registration:	GBP153	Reg Expiry:	05 Jan 2019
WoF Expiry:	25 Oct 2019	Odometer:	160,566 Kms	Good No:	18618607
VIN:	7AT0H603X11125313	Next Service:	163900	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs


Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments
Interior Comments

Seats	stains
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Tidy

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0	mm	
Right front	5.0	mm	
Left rear	5.0	mm	
Right rear	3.0	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Stuart Melbourne

Date: 29 Oct 2018

I have read and understood this condition guide.

Name:

Signature: