# Turners


# Basic Vehicle Condition Guide

Report ID: 18,619,799
Version: 1
Created: 31 Oct 2018

| | | | | | |
|---|---|---|---|---|---|
| **Make:** | Nissan | **Model:** | Navara | **Body Style:** | Utility |
| **Year:** | 2016 | **Registration:** | JTJ408 | **Reg Expiry:** | 28 Apr 2019 |
| **WoF Expiry:** | 29 Apr 2019 | **Odometer:** | 30,147 Kms | **Good No:** | 18619799 |
| **VIN:** | MNTCB4D23A000963 | **Next Service:** | 49711 | **Service History:** | No |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs




Note: some defects & blemishes may not be displayed in the diagram

## Body Inspection Comments

## Conditions During Body Inspection: Wet

## Under Carriage & Under Bonnet Inspection Comments

Dirty

## Interior Comments

| | |
|---|---|
| Seats | Good |
| Carpets | Good |
| Panels | Average |
| Dashboard | Good |

## General Comments

## Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 2 mm | | |
| Right front | 2 mm | | |
| Left rear | 4 mm | | |
| Right rear | 4 mm | | |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | ✔ | | |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | ✔ | | |

Inspected by: Stuart Melbourne Date: 31 Oct 2018

I have read and understood this condition guide. Name: ..... Signature: .....