

Report ID: 18,619,813 Version: 1 Created: 31 Oct 2018

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A	
Year:	2016	Registration:	JTJ406	Reg Expiry:	28 Apr 2019	Engine	-			
WoF Expiry:	29 Apr 2019	Odometer:	27,487 Kms	Good No:	18619813	Oil level	~			
VIN:	MNTCB4D23A000996	Next Service:	47,200kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	s sc		SD	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	SC DI			715	HIL	Operation	~			
PT = paint def	ect NP	F		$\left[\left(\right) \right]$		Noise	~			
C = crack					S	Clutch			~	
P = pin dent	HID				74116	CV joints	~			
* = decals SC 99 S						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S P S P						Performance	~			
Body Inc	portion Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments R/H tail light chipped.						Tyres (lowest observed trea	d depth	of tyre	es)	
Stone chipped screen .						Left front 8 mi			mm	
						Right front	8	3	mm	
						Left rear		5	mm	
Conditions During Body Inspection: Dry						Right rear	4 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	uspension			
Tidy .						Suspension performance	~			
Steering performance							~			
Shock absorbers							~			
		Air Conditioning / Heater								
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets	-					Indicators	~			
Panels	scratched	drivers door pan	el .			Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Good 4WD	auto d/cab ute .					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Increate	Inspected by: Daryll Timms Date: 31 Oct 2018									
Inspected by: Daryii Himms Date: 31 Oct 2018										

I have read and understood this condition guide.

Name:

Signature: