



# Turners Certified Imports 50 Point Check

Report ID: 18,620,148  
Version: 1  
Created: 05 Nov 2018

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Nissan Body Style: SUV  
Model: Dualis Odometer: 36,239 Kms  
Year: 2010 VIN: 7AT0DH7HX18251612

### Under Carriage & Under Bonnet Inspection Comments

### General Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

### Electrical

Battery	<input checked="" type="checkbox"/>
Head lights	<input checked="" type="checkbox"/>
Tail lights	<input checked="" type="checkbox"/>
Indicators	<input checked="" type="checkbox"/>
Dashboard warning lights	<input checked="" type="checkbox"/>
Wipers (front & rear)	<input checked="" type="checkbox"/>
Window winder FL	<input checked="" type="checkbox"/>
Window winder FR	<input checked="" type="checkbox"/>
Window winder RL	<input checked="" type="checkbox"/>
Window winder RR	<input checked="" type="checkbox"/>
Rear view mirrors	<input checked="" type="checkbox"/>
Radio (basic test only)	<input checked="" type="checkbox"/>
CD (basic test only)	<input checked="" type="checkbox"/>
Reversing camera	<input checked="" type="checkbox"/>

### Transmission & Drive

Operation	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>
Clutch	<input type="checkbox"/>
CV joints	<input checked="" type="checkbox"/>
Wheel bearings	<input checked="" type="checkbox"/>
Wheel balance	<input checked="" type="checkbox"/>

### Brakes

Performance	<input checked="" type="checkbox"/>
Hand Brake	<input checked="" type="checkbox"/>

### Keys & Locking

Central locking	<input checked="" type="checkbox"/>
Remote locking	<input checked="" type="checkbox"/>
Number of keys	2

### Engine

Oil level	<input checked="" type="checkbox"/>
Smoke & fumes	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>

### Cooling System

Coolant condition	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>

### Suspension

Suspension performance	<input checked="" type="checkbox"/>
Steering performance	<input checked="" type="checkbox"/>
Shock absorbers	<input checked="" type="checkbox"/>

### Tyres (lowest observed tread depth)

Left front	6.5 mm
Right front	6.6 mm
Left rear	6.5 mm
Right rear	6.9 mm
Spare	Yes
Tools	<input checked="" type="checkbox"/>

### Interior

AC Operation	<input checked="" type="checkbox"/>
Heater fan	<input checked="" type="checkbox"/>
Seatbelts	<input checked="" type="checkbox"/>
Horn	<input checked="" type="checkbox"/>

### Turners Certified Key

✓ = Pass      ✗ = Fail  
• = Not applicable for this vehicle

Inspected by: Ian Dunn

Date: 05 Nov 2018

I have read and understood this condition guide.

Name: .....

Signature: .....