

Report ID: 18,622,381 Version: 1 Created: 31 Oct 2018

| Make: | Toyota | Model: | Camry | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|---------------------------------|-----------------------|--|--------|------|--------|
| Year: | 2016 | Registration: | LSQ639 | Reg Expiry: | 04 Jun 2019 | Engine | 1 | | I |
| WoF Expiry: | 06 Nov 2019 | Odometer: | 76,119 Kms | Good No: | 18622381 | Oil level | ~ | | |
| VIN: | 6T1BF3FK00X081848 | Next Service: | 86000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | SC | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | DW 6/6 | | | TIS | HILW | Operation | ~ | | |
| PT = paint defe | | | | $\left[\right] \left[\right]$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIC | | | | 세비 | CV joints | ~ | | - |
| * = decals | sc 916 | | | - NL | ALL ALL | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs D W | | | | | | Performance | ~ | | |
| D. L.L. | | Note: som | ne defects & blemishes | may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Stone chips front screen | | | | | Left front 4 mm | | | | |
| | | | | | | Right front | | - | mm |
| | | | | | | Left rear | | | mm |
| Condition | as During Padulas | naction | | | | Right rear | | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear 4 n Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | - | • | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats Good | | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | I | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | | | |
| Road Conditions During Test Drive: Drv | | | | | | Central locking | 2 | | |
| Koad Con | attions During Tes | u Drive: | Dry | | | Remote locking | v v | | |
| Engine Ti | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | ~ |
| | | P | | | | | | | |
| Inspected by: Brian Hill Date: 31 Oct 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: