

Basic Vehicle Condition Guide

Report ID: 18,622,594


Version:

Created: 02 Nov 2018

Make: Model: Mazda **Body Style:** Wagon Atenza Year: 2014 Registration: LCU636 Reg Expiry: 23 Dec 2018 **WoF Expiry: Odometer:** 13 Nov 2019 **Good No:** 18622594 90,940 Kms VIN: **Next Service: Service History:** 7AT0C139X17111103 90334 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

Interior Comments				
Seats		Good		
Carpet	:S	Good		
Panels		Good		
Dashb	oard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 02 Nov 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	VVV		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	3	mm
Right front	4	4	mm
Left rear	į	5	mm
Right rear	3	3	mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	\(\times \) \(\t		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: