

Report ID: 18,624,194 Version: 1 02 Nov 2018 Created:

Make:	BMW	Model:	Х3	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2005	Registration:	GCG596	Reg Expiry:	13 Jan 2019	Engine		1	L	
WoF Expiry:	18 Jul 2019	Odometer:	139,196 Kms	Good No:	18624194	Oil level	~			
VIN:	WBAPA92020WB3570	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		<b>C</b> 1 1			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	· ·			
Key:	sc	-0	D SD			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent				1n-		Operation	~			
R = rust				10	THIA	Noise	~			
PT = paint defe C = crack				$+$ $\vee$	SC	Clutch	•		~	
P = pin dent						CV joints	~		•	
* = decals	s sc PIP			AL.	EIRS	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs W S D W						Performance				
		Noto: com			laved in the diagram	Hand Brake	V			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							<b>/</b>			
					Tyres (lowest observed tread depth of tyres)					
						Left front	4 mm			
						Right front		1	mm	
						Left rear	4 mm			
Conditions During Body Inspection: Dry						Right rear				
Under Carriage & Under Pennet Increation Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Airbag light on Oil leak						Suspension performance	~			
Underbody oxidisation						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~			
						Indicators	~			
Panels	Average					Dashboard warning lights		~		
Dealtheas	Average					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
			,			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: John Lindsay Date: 02 Nov 2018										

I have read and understood this condition guide.

Name: .....

Signature: .....