

Basic Vehicle Condition Guide

Report ID: 18,625,043


Version: 2

Created: 26 Nov 2018

Make: Model: Toyota Highlander **Body Style:** SUV Year: 2007 Registration: EEK375 Reg Expiry: 19 Jan 2019 WoF Expiry: **Odometer: Good No:** 28 Nov 2019 173,327 Kms 18625043 VIN: JTEDS41A102017433 Next Service: 183500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Tow eye covers missing front bumper,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---|--|--|
| Seats | Average | | |
| Carpets | middle console lid ripped , | | |
| Panels | Average | | |
| Dashboard | radio screen not working but stereo works , | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

| Create | u. 20 | J 110V 2 | .010 |
|------------------------------|--------------|----------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | <i>v</i> | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | V V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | ⊥ ≥s) |
| Left front | I | 7 | mm |
| Right front | | 7 | mm |
| Left rear | | 4 | mm |
| Right rear | 4 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | ı |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | | | |
| Window winder FR | V V | | |
| Window winder RL | ~ | | |
| Window winder RR | <i>v</i> | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 3 | | 1 |
| Central locking | | | |
| Remote locking | <i>y</i> | | |
| Sat. Nav. (basic test only) | | | ., |
| Reversing camera | ~ | | |
| - neversing currera | | | |
| Date: 26 Nov 20 | 18 | | |
| | | | |

I have read and understood this condition guide.

Name:

Signature: