

Basic Vehicle Condition Guide

Report ID: 18,625,516

Pass

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)

Number of keys

Central locking

Operation

Head lights

Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 05 Nov 2018

Fail

N/A

1

mm

mm

mm

 mm

5.6

5.3

4.6

1

1

~

/

1


~

Yes

Make: Model: Volkswagen Polo **Body Style:** Hatchback Year: Registration: **Reg Expiry:** 1998 **DHH229** 04 Jan 2019 WoF Expiry: **Odometer:** 08 Feb 2019 **Good No:** 160,229 Kms 18625516 VIN: WVWZZZ6NZWW1507 **Next Service: Service History:** n/a No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left brake light out Hood liner loose

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

Interior Comm	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Engine misfire

Road Conditions During Test Drive: Drv

media comanicons 2 annig rest 2 men		+	
	Remote locking	'	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)	V	
Evidence of Cam Belt Replacement: No	Reversing camera	~	
Inspected by: lan Dunn	Date: 05 Nov 2018		
I have read and understood this condition guide.	Name: Signature:		