

Basic Vehicle Condition Guide

Report ID: 52,420


Version: 1

Created: 10 Dec 2018

Make: Model: Mazda Mazda3 **Body Style:** Sedan Year: 2008 Registration: ETL406 Reg Expiry: 14 Dec 2018 WoF Expiry: **Odometer:** 18 Nov 2019 80,500 Kms **Good No:** 18625707 VIN: JM0BK103200414100 **Next Service:** 87500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jens Date: 19 Nov 2018

Name:

	D	F-11	N1/A
Engino	Pass	Fail	N/A
Engine Oil level			1
Smoke & fumes	-		
	\(\times \)		
Performance	•		
Noise	<i>V</i>		
Cooling System			1
Coolant condition	•		
Performance	•		
Radiator / Hoses (visual)	<i>'</i>		
Transmission			ı
Operation	•		
Noise	-		
Clutch			~
CV joints	-		
Wheel bearings	•		
Brakes	Ι		1
Performance	~		
Hand Brake	'	_	
Tyres (lowest observed tread	d depth	of tyre	-
Left front	4.0		mm
Right front	4	4.0	
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	•		
Air Conditioning / Heater	1		
Operation	'		
Electrical / Accessories	I		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)			
Window winder FL	\(\times \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Signature: