

Report ID: 18,627,180 Version: 4 26 Nov 2018 Created:

Make:	Toyota	Model:	Altezza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2001	Registration:	LHJ834	Reg Expiry:	13 Apr 2019	Engine			1
WoF Expiry:	06 Oct 2019	Odometer:	214,511 Kms	Good No:	18627180	Oil level	~		
VIN:	7AT0H639X10077514	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		+
	port is not a warranty		с I I			Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S	-0	LIS		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	BIDS	Operation	~		T
R = rust				10	7HH	Noise	~		
PT = paint def	ect III			+		Clutch	-		
C = crack P = pin dent	Ho						~		
* = decals	sc pp					CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs W S W						Brakes			
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	.0	mm
						Right front	3	3	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.	.0	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			_
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		1
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		+
						CD (basic test only)			~
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		1
						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1		<u> </u>
Inspecte	d by: Stuart Melbourr	Date: 08 Nov 20	18						
I have read and understood this condition guide. Name:									