

Basic Vehicle Condition Guide

Report ID: 18,628,297


Version: 1

Created: 13 Nov 2018

Make: Model: Mitsubishi Outlander **Body Style:** SUV Year: 2013 Registration: **JUU618** Reg Expiry: 01 Jan 2019 WoF Expiry: **Odometer: Good No:** 25 Jun 2019 40,636 Kms 18628297 VIN: JMFXTGF7WDZ00019 Next Service: Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right tail light condensation

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Carpets missing		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by:

ss	Fail	N/A
	1 an	IN/A
		+ .
		-
oth	n of tyre	es)
	3	mm
3		mm
6		mm
6		mm
	Yes	
	1	
	.1	1
		~
		1
		1
	_	

I have read and understood this condition guide.

Name:

Signature: