

Basic Vehicle Condition Guide

Report ID: 18,628,444


Version:

Created: 07 Nov 2018

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2007 Registration: GMF361 Reg Expiry: 01 Apr 2019 WoF Expiry: **Odometer:** 03 Apr 2019 **Good No:** 18628444 159,665 Kms VIN: 7AT0GK0CX12156279 **Next Service: Service History:** 163,000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LF and RR windows not working.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Play in both front top strut mounts.

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

06 Nov 2018 Inspected by: Scott Willoughby Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>V</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 8 | .0 | mm |
| Right front | 8.0 | | mm |
| Left rear | 2.0 | | mm |
| Right rear | 2.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | | ~ | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | \(\times \) | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | | ~ | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | | ~ | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Signature: