

Report ID: 52,298 Version: 2 07 Mar 2019 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	FKH157	<b>Reg Expiry:</b>	31 Jul 2019	Engine			
WoF Expiry:	09 Nov 2019	Odometer:	105,550 Kms	Good No:	18628617	Oil level	~		
VIN:	JF1BM9K92AG006550	Next Service:	113500	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
			D			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$	7014	Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	- Alk			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Rodular		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front 3.0 m			mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	<b>C</b> 1					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Yes Kms: 103,470						Reversing camera			~
	•								<b>_</b>
Inspected by: Jens Date: 12 Nov 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....