

Report ID: 18,630,899 Version: 3 07 Dec 2018 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2000	Registration:	EUW77	Reg Expiry:	21 Dec 2018	Engine			
WoF Expiry:		Odometer:	164,572 Kms	Good No:	18630899	Oil level	~		
VIN:	7A8GF090708004707	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S PT SC W	-0	SD SD		sc	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	PT SC W			The	BID SW	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	R PT SC	Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals	S PT SC			AL.	ELTR PT	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S PT W S PT D						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1016.301	le delects & blemisnes	s may not be disp	layed in the diagram			ofture	
						Tyres (lowest observed tread depth of tyres)   Left front 4			
						Right front		4	mm
						Left rear		5 mm	
								7	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Both remotes not working						Suspension			
Oil leak						Suspension performance	~		
Underbody oxidisation						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Holes in passanger and rear seat stains on seats						Electrical / Accessories			
Seats		g				Head lights	~		
Carpets	Average					Tail lights	~		
· · ·	Average					Indicators	~		
Panels	/ verage					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (	<u>Comments</u>					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ning Mechanism:	Cambel				Remote locking		~	
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
		chient. N	10	11115.		Reversing camera			~
Inspected by: John Lindsay Date: 07 Dec 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....