


|                    |                  |                      |             |                         |             |
|--------------------|------------------|----------------------|-------------|-------------------------|-------------|
| <b>Make:</b>       | Honda            | <b>Model:</b>        | Accord      | <b>Body Style:</b>      | Sedan       |
| <b>Year:</b>       | 2000             | <b>Registration:</b> | ZY6190      | <b>Reg Expiry:</b>      | 17 Apr 2019 |
| <b>WoF Expiry:</b> | 19 Mar 2019      | <b>Odometer:</b>     | 188,133 Kms | <b>Good No:</b>         | 18630984    |
| <b>VIN:</b>        | MRHCG5640YP01005 | <b>Next Service:</b> | 192000      | <b>Service History:</b> | Yes         |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Stone chips front screen. Both headlight lens dirty.

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

FWD.

**Interior Comments**

|           |                                   |
|-----------|-----------------------------------|
| Seats     | Good n Drivers seat sign of wear. |
| Carpets   | Good                              |
| Panels    | Good                              |
| Dashboard | Good                              |

**General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 100,000

|   | Pass | Fail | N/A |
|---|------|------|-----|
| <b>Engine</b>                                       |      |      |     |
| Oil level   | ✗    |      |     |
| Smoke & fumes                                       | ✗    |      |     |
| Performance   | ✗    |      |     |
| Noise   | ✗    |      |     |
| <b>Cooling System</b>                               |      |      |     |
| Coolant condition                                   | ✗    |      |     |
| Performance   | ✗    |      |     |
| Radiator / Hoses (visual)                           | ✗    |      |     |
| <b>Transmission</b>                                 |      |      |     |
| Operation   | ✗    |      |     |
| Noise   | ✗    |      |     |
| Clutch  |      |      | ✗   |
| CV joints   | ✗    |      |     |
| Wheel bearings                                      | ✗    |      |     |
| <b>Brakes</b>                                       |      |      |     |
| Performance   | ✗    |      |     |
| Hand Brake  | ✗    |      |     |
| <b>Tyres</b> (lowest observed tread depth of tyres) |      |      |     |
| Left front  | 6    | mm   |     |
| Right front   | 6    | mm   |     |
| Left rear   | 6    | mm   |     |
| Right rear  | 6    | mm   |     |
| Spare   |      | Yes  |     |
| <b>Suspension</b>                                   |      |      |     |
| Suspension performance                              | ✗    |      |     |
| Steering performance                                | ✗    |      |     |
| Shock absorbers                                     | ✗    |      |     |
| <b>Air Conditioning / Heater</b>                    |      |      |     |
| Operation   | ✗    |      |     |
| <b>Electrical / Accessories</b>                     |      |      |     |
| Head lights   | ✗    |      |     |
| Tail lights   | ✗    |      |     |
| Indicators  | ✗    |      |     |
| Dashboard warning lights                            | ✗    |      |     |
| Wipers (front & rear)                               | ✗    |      |     |
| Window winder FL                                    | ✗    |      |     |
| Window winder FR                                    | ✗    |      |     |
| Window winder RL                                    | ✗    |      |     |
| Window winder RR                                    | ✗    |      |     |
| Rear view mirrors                                   | ✗    |      |     |
| Radio (basic test only)                             | ✗    |      |     |
| CD (basic test only)                                | ✗    |      |     |
| Number of keys                                      | 1    |      |     |
| Central locking                                     | ✗    |      |     |
| Remote locking                                      | ✗    |      |     |
| Sat. Nav. (basic test only)                         |      |      | ✗   |
| Reversing camera                                    |      |      | ✗   |

Inspected by: Eddie Marsters

Date: 09 Nov 2018

I have read and understood this condition guide.

Name: .....

Signature: .....