


<b>Make:</b>	Skoda	<b>Model:</b>	Fabia	<b>Body Style:</b>	Hatchback
<b>Year:</b>	2014	<b>Registration:</b>	HGR409	<b>Reg Expiry:</b>	23 Feb 2019
<b>WoF Expiry:</b>	15 Mar 2019	<b>Odometer:</b>	163,543 Kms	<b>Good No:</b>	18631093
<b>VIN:</b>	TMBFP65J7E3030449	<b>Next Service:</b>		<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Front tow eye cover missing  
LF park plate light not working  
LR brake light lens broken  
Rear wiper cover missing  
Rear bumper and RR quarter panel misaligned (accident damaged)

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

## Under Carriage & Under Bonnet Inspection Comments

Transmission mount cracked  
Oil leaks in transmission and engine area  
Underbody dent and underbody tray damaged

## Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Good

## General Comments

Arm rest broken  
Sunglasses tray broken  
Boot cover missing

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	5	mm	
Left rear	5	mm	
Right rear	5	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Bobby Zhong

Date: 24 Nov 2018

I have read and understood this condition guide.

Name: .....

Signature: .....