


| | | | | | |
|--------------------|-------------------|----------------------|------------|-------------------------|-------------|
| Make: | Honda | Model: | Civic | Body Style: | Hatchback |
| Year: | 2012 | Registration: | GPU19 | Reg Expiry: | 04 Dec 2018 |
| WoF Expiry: | 05 Dec 2018 | Odometer: | 51,418 Kms | Good No: | 18631174 |
| VIN: | SHHFK2860CU304244 | Next Service: | 61000 | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs


Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
Interior Comments

| | |
|-----------|------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✗ | | |
| Smoke & fumes | ✗ | | |
| Performance | ✗ | | |
| Noise | ✗ | | |
| Cooling System | | | |
| Coolant condition | ✗ | | |
| Performance | ✗ | | |
| Radiator / Hoses (visual) | ✗ | | |
| Transmission | | | |
| Operation | ✗ | | |
| Noise | ✗ | | |
| Clutch | | | ✗ |
| CV joints | ✗ | | |
| Wheel bearings | ✗ | | |
| Brakes | | | |
| Performance | ✗ | | |
| Hand Brake | ✗ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 5 | mm | |
| Right front | 5 | mm | |
| Left rear | 5 | mm | |
| Right rear | 5 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✗ | | |
| Steering performance | ✗ | | |
| Shock absorbers | ✗ | | |
| Air Conditioning / Heater | | | |
| Operation | ✗ | | |
| Electrical / Accessories | | | |
| Head lights | ✗ | | |
| Tail lights | ✗ | | |
| Indicators | ✗ | | |
| Dashboard warning lights | ✗ | | |
| Wipers (front & rear) | ✗ | | |
| Window winder FL | ✗ | | |
| Window winder FR | ✗ | | |
| Window winder RL | ✗ | | |
| Window winder RR | ✗ | | |
| Rear view mirrors | ✗ | | |
| Radio (basic test only) | ✗ | | |
| CD (basic test only) | ✗ | | |
| Number of keys | 2 | | |
| Central locking | ✗ | | |
| Remote locking | ✗ | | |
| Sat. Nav. (basic test only) | | | ✗ |
| Reversing camera | ✗ | | |

Inspected by: Brad Lucas

Date: 11 Nov 2018

I have read and understood this condition guide.

Name:

Signature: