

Report ID: 18,631,525 Version: 2 09 Nov 2018 Created:

Make:	Hyundai	Model:	Santa Fe	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	DNK401	Reg Expiry:	24 Dec 2018	Engine		I	1
WoF Expiry:	14 Apr 2019	Odometer:	207,511 Kms	Good No:	18631525	Oil level	×		
VIN:	KMHSH81DR6U05892	Next Service:	215000	Service Histor	<b>y:</b> Yes	Smoke & fumes	×		
						Performance	×		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	×		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	×		
		_				Performance	×		
Key:		-0	SP SP	-161-	Р	Radiator / Hoses (visual)	×		
S = scratch						Transmission			
D = dent						Operation	×		
R = rust PT = paint defe				$\int$	THA	Noise	×		
C = crack						Clutch			×
P = pin dent					741L	CV joints	×		
* = decals				-NL		Wheel bearings	×		
SC = stone chips						Brakes			
W = significant scuffs						Performance X			
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	×		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		of tyre	
Stone chips front screen.Both headlight lens dirty.Rear bumper towing eye plug missing.								mm	
					Right front		.5	 mm	
						Left rear		 B	mm
Canditian		a a sti a sa	D.			Right rear			 mm
Conditions During Body Inspection: Dry						Right rear 6 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		·				Suspension performance	×		
						Steering performance	×		
						Shock absorbers	×		
						Air Conditioning / Heater	^		
						Operation X			
Interior Comments						Electrical / Accessories			
Good Good						Head lights	×		
						Tail lights	×		
Carpets	Good						×		
Danala	Good					Dashboard warning lights	×		$\left  - \right $
Panels						Wipers (front & rear)	×		$\left  - \right $
Dashboa	rd Good					Window winder FL	×		
						Window winder FR	×		
General Comments						Window winder RL	×		
Left front n right rear windows not working at drivers door switch.						Window winder RR	×		<u> </u>
						Rear view mirrors	×		
						Radio (basic test only)	×		
						CD (basic test only)	×		
						Number of keys	2		L
Dead Conditions During Test Driver D						Central locking	2 X		
Road Conditions During Test Drive: Dry						Remote locking	×		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			×
Evidence of Cam Belt Replacement: Yes Kms: 191,390						Reversing camera	×		
	•						^		<u> </u>
Inspected by: Eddie Marsters Date: 09 Nov 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....