

<b>Make:</b> Suzuki	<b>Model:</b> Escudo	<b>Body Style:</b> Wagon
<b>Year:</b> 1993	<b>Registration:</b> YG2062	<b>Reg Expiry:</b> 02 Jan 2019
<b>WoF Expiry:</b> 26 Dec 2018	<b>Odometer:</b> 242,784 Kms	<b>Good No:</b> 18632147
<b>VIN:</b> 7A8GK4M0799864895	<b>Next Service:</b> unknown	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
 D = dent  
 R = rust  
 PT = paint defect  
 C = crack  
 P = pin dent  
 \* = decals  
 SC = stone chips  
 W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

**Body Inspection Comments**

Body filler in front right guard & bumper.  
 Wrap on bonnet.  
 Front bumper loose.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Oil leaks around tappet cover.

**Interior Comments**

Seats	average, rip on front left seat.
Carpets	Poor
Panels	speaker holes cut into rear door. no rear ashtray
Dashboard	radio surround loose, screw holes .

**General Comments**

Untidy & higher kms, but OK.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt  
 Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4.0	mm	
Right front	6.0	mm	
Left rear	2.0	mm	
Right rear	1.6	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Daryll Timms Date: 12 Nov 2018

I have read and understood this condition guide. Name: ..... Signature: .....