

Report ID: 18,632,374 Version: 1 15 Nov 2018 Created:

Make:	Peugeot	Model:	307	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	<b>Registration:</b>	DYC255	Reg Expiry:	29 Jul 2019	Engine	I		L
WoF Expiry:	03 May 2019	Odometer:	111,478 Kms	Good No:	18632374	Oil level	~		
VIN:	VF33CRHRJ84744408	Next Service:	118633	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			I
a full mechar	nical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-	Р	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			X.	Transmission	•		L
D = dent	s sc			The		Operation	~		
R = rust PT = paint def				$\int$	JHIA	Noise	~		
C = crack				+	SC	Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc pp					Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SW S						Performance	~		<u> </u>
		Noto: con		may not be disp	laved in the diagram	Hand Brake	<i>v</i> <i>v</i>		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofter	
						Left front	Tyres (lowest observed tread depth of tyres)		
								5	mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	5	5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	innage & onder bor	metmspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
	_					Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Xinghui Lin Date: 15 Nov 2018									
I have read and understood this condition guide. Name:									