

			An Conditioning / neater		
		Operation	~		
Interior Comments		Electrical / Accessories	Electrical / Accessories		
Seats	Average	Head lights	~		
Carpets	Average	Tail lights	~		
		Indicators	~		
Panels	Average	Dashboard warning lig	ghts 🖌		
Dashboard	Average	Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		
General Comments		Window winder RL	~		
RPM gauge laggy		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)	~		
		Number of keys	2		
Road Conditions During Test Drive: Wet		Central locking	~		
	-	Remote locking	~		
ngine Timing I	Mechanism: Cambelt	Sat. Nav. (basic test on	ly)	~	

Evidence of Cam Belt Replacement: Yes

Inspected by: Ca Thach

Date: 14 Nov 2018

Reversing camera

I have read and understood this condition guide.

Name:

Kms:

96,000

~