

Report ID: 18,635,652 Version: 3 14 Feb 2019 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	Registration:	DUT218	Reg Expiry:	04 Jun 2019	Engine			
WoF Expiry:	12 Feb 2020	Odometer:	283,992 Kms	Good No:	18635652	Oil level	~		
VIN:	MM0UNY0E30062147	Next Service:	288000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta harra nat	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	P SD	-161-	S R	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	SD SD	Operation	~		
R = rust PT = paint defe				í l	JHIH	Noise	~		
C = crack				+	PT	Clutch	~		
P = pin dent						CV joints	•		~
* = decals	sc 916			- AL	EIIP I	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note [,] som	e defects & blemishes	may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftyre))
RR brake lens damaged Front bumper missing trim						Tyres (lowest observed tread depth of tyres) Left front 6.0 mm			
	5e					Right front			mm
						Left rear	6.		mm
			_			Right rear	4.		-
Conditions During Body Inspection: Dry						Spare	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Seats									
Carpets	Average					Tail lights Indicators	v		
	Average					Dashboard warning lights	v		
Panels						Wipers (front & rear)	レ レ		
Dashboa	Good Good					Window winder FL	~		
]	Window winder FL	~		
General (Comments					Window winder FR			
						Window winder RL	v		
						Rear view mirrors	~		
						Radio (basic test only) CD (basic test only)	ン ン		
						Number of keys			
						-	1		
Road Conditions During Test Drive: Wet						Central locking	v		
Engine Tir	ming Mechanism:	Cambelt	t			Remote locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 276,900						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 276,900 Reversing camera									~
Inspected by: Bobby Zhong Date: 12 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: