

Report ID: 18,636,145 Version: 1 16 Nov 2018 Created:

| Make: | Peugeot | Model: | 306 | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|----------------|------------------------|-------------------|----------------------|--|--------|------|-----|
| Year: | 1999 | Registration: | | Reg Expiry: | 19 Dec 2018 | Engine | | | |
| WoF Expiry: | | Odometer: | 231,607 Kms | Good No: | 18636145 | Oil level | ~ | | |
| VIN: | VF37ALFYE32679657 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | 113771211232079037 | | | | | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | | | |
| Key: | L | -0 | D PT S SC | | | Radiator / Hoses (visual) | レ レ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | | | | | | |
| R = rust | | | | 10 | SHIK | Operation | ~ | | |
| PT = paint def | ect | | | + | PT | Noise | ~ | | |
| C = crack P = pin dent | LHC | | | - | | Clutch | ~ | | |
| * = decals | sc dk | | | | | CV joints | ~ | | |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs W PT P W | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Ins | pection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Head light lenses cracked | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Rust developing in right hand sill area | | | | | | Left front | 1 | .5 | mm |
| | | | | | | Right front | 1 | .5 | mm |
| | | | | | | Left rear | 1 | .5 | mm |
| Conditions During Body Inspection: Dry | | | | | Right rear | 1.5 m | | mm | |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Minor rust left front lower radiator support panel Gearbox oil leaks | | | | | | Suspension performance | ~ | | |
| Rear brake | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | | ~ | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | door trim | material loose | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | · · | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| A/C not cold Clutch pedal heavy | | | | | | Window winder RR | ~ | | |
| | ai neavy | | | | | Rear view mirrors | V | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | I | |
| | | | | | | Central locking | · • | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: Yes Kms: 126,000 | | | | | | Reversing camera | | | ~ |
| | • | | | | | | | | - |
| Inspected by: Greg Morgan Date: 16 Nov 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: