

Report ID: 18,636,178 Version: 2 08 Dec 2018 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback] [Pass	Fail	N/A
Year:	2017	Registration:	KJR976	Reg Expiry:	21 Nov 2018	Engine			
WoF Expiry:		Odometer:	63,867 Kms	Good No:	18636178	Oil level	~		
VIN:	KMHD351EMHU38428	Next Service:		Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I и			Noise	~		
l'his report is diagnostic te	a guide only. Conside sting undertaken. The	eration is made vehicle has beer	for age and milea odriven up to 50kr	ige. Parts have not n/h from cold. The '	been dismantled or /endor recommends	Cooling System	•		
a full mechan	ical inspection prior to	purchase and th	his can be arranged	l for an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	PP			Radiator / Hoses (visual)	~		
S = scratch	STE	A U			The second	Transmission	•		L
D = dent	ISC 6/6				EL SC	Operation	~		
R = rust PT = paint defe					THIA	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	P PIE					Wheel bearings	~		<u> </u>
SC = stone chi	/	20		La	~	Brakes	•		L
W = significan	t scuffs			- Wr		Performance	~		
		Note com	e defects & blamic	hes may not be disp	laved in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Stonechips on windscreen						Tyres (lowest observed tread depth of tyres) Left front 7			
								7	mm
						Right front		7	mm
						Left rear	<u> </u>		mm
Conditions During Body Inspection: Wet						Right rear	3 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage & onder bor	meenspeede	<u>in comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		-
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
	Good					Electrical / Accessories			T
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concurl						Window winder FR	~		<u> </u>
General C	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
Engine Th	ming Machaniana	Time !	Chain			Remote locking	~		
-	ming Mechanism:	Timing (K and k		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Ca Thach					Date: 08 Dec 20	18		

I have read and understood this condition guide.

Name:

Signature: