

Report ID: 56,342


Version: 2

Created: 14 Feb 2019

Make:	Holden	Model:	Captiva 5	Body Style:	SUV
Year:	2007	Registration:	DQZ725	Reg Expiry:	02 Jul 2019
WoF Expiry:	03 Jan 2020	Odometer:	135,300 Kms	Good No:	18636726
VIN:	KL3CD26GJ7B019467	Next Service:	Just Serviced	Service History	/ : No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments					
Seats	Average				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Dry

Timing Chain **Engine Timing Mechanism:**

Evidence of Cam Belt Replacement: Not Applicable Kms:

07 Jan 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	· ·		<u> </u>
Tyres (lowest observed tread			
Left front		.0	mm
Right front Left rear		.0	mm
		.0	mm
Right rear	/	.0	mm
Spare Suspension		Yes	
Suspension performance	·/		
Steering performance	V V		
Shock absorbers	<i>y</i>		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	'		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

Signature: