

Report ID: 18,637,588 Version: 1 06 Dec 2018 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	<b>Registration:</b>	KMJ396	Reg Expiry:	11 Apr 2019	Engine	1		I
WoF Expiry:	11 Apr 2020	Odometer:	41,795 Kms	Good No:	18637588	Oil level	~		
VIN:	6FPAAAJGATGA98428	Next Service:	40000	Service Histor	<b>y:</b> Yes	Smoke & fumes	V		
						Performance	~		
	port is not a warranty a guide only. Conside	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
diagnostic tes	sting undertaken. The	vehicle has beer	n driven up to 50km/ł	n from cold. The	Vendor recommends	Cooling System			L
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	EI SP	Operation	~		
R = rust				1 M	JHH	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc pp			AL.		Wheel bearings	~		<u> </u>
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		T
		Noto: con	ne defects & blemishe		laved in the diagram	Hand Brake	~		
————————————————————————————————————	ection Comments	Note. son	le délects & bieffisile	s may not be disp	bayed in the diagram		•		
Stone chips on windscreen Front tyre camber wear						Tyres (lowest observed tread depth of tyres)			
Front tyre C	amber wear					Left front	4	-	mm
						Right front	4		mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		<u> </u>
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		<u> </u>
						Rear view mirrors	~	<u> </u>	1
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		+
						Number of keys	2		L
Road Can	ditions During Test	t Drivo:				Central locking	~		
	unions During Test		Wet			Remote locking	~		<u> </u>
Engine Tir	ning Mechanism:	Cambel	t			Sat. Nav. (basic test only)	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		<u> </u>
		•					•		
Inspected	d by: Bobby Zhong					Date: 06 Dec 20	18		
•									

I have read and understood this condition guide.

Name: .....

Signature: .....