

## **Basic Vehicle Condition Guide**

Report ID: 18,638,030

Version:

Engine

Oil level

Created: 19 Nov 2018


Fail

N/A

Make: Model: CRV Honda **Body Style:** Wagon Year: 1997 Registration: EBU57 Reg Expiry: 21 Nov 2018 **Odometer:** WoF Expiry: 08 Dec 2018 166,155 Kms **Good No:** 18638030 VIN: 7A88G7H0707021273 Next Service: 173000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Covers missing from front bumper Extended bumper cover loose

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Oil leak

Underbody oxidisation

| Interior Comment | <u>S</u>                  |
|------------------|---------------------------|
| Seats            | Marks and stains on seats |
| Carpets          | Marks on carpets          |
| Panels           | Average                   |
| Dashboard        | Average                   |

## **General Comments**

Knock in front suspension

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No Kms:

| Smoke & fumes                | ~        |       |                                       |
|------------------------------|----------|-------|---------------------------------------|
| Performance                  | ~        |       |                                       |
| Noise                        | ~        |       |                                       |
| Cooling System               |          |       |                                       |
| Coolant condition            | ~        |       |                                       |
| Performance                  | ~        |       |                                       |
| Radiator / Hoses (visual)    | ~        |       |                                       |
| Transmission                 | ı        | ı     |                                       |
| Operation                    | ~        |       |                                       |
| Noise                        | ~        |       |                                       |
| Clutch                       |          |       | ~                                     |
| CV joints                    | ~        |       |                                       |
| Wheel bearings               | ~        |       |                                       |
| Brakes                       | I        |       |                                       |
| Performance                  | ~        |       |                                       |
| Hand Brake                   | ~        |       |                                       |
| Tyres (lowest observed tread | l depth  | of ty | res)                                  |
| Left front                   |          | 5     | mm                                    |
| Right front                  |          | <br>3 | mm                                    |
| Left rear                    | 4 mm     |       | mm                                    |
| Right rear                   | 4 mm     |       |                                       |
| Spare                        |          | Yes   |                                       |
| Suspension                   |          |       |                                       |
| Suspension performance       |          | ~     |                                       |
| Steering performance         | ~        |       |                                       |
| Shock absorbers              | ~        |       |                                       |
| Air Conditioning / Heater    | <u> </u> |       |                                       |
| Operation                    | ~        |       |                                       |
| Electrical / Accessories     |          |       |                                       |
| Head lights                  | ~        |       |                                       |
| Tail lights                  | ~        |       |                                       |
| Indicators                   | ~        |       |                                       |
| Dashboard warning lights     | ~        |       |                                       |
| Wipers (front & rear)        | 1        |       |                                       |
| Window winder FL             | V        |       |                                       |
| Window winder FR             | ~        |       |                                       |
| Window winder RL             | ~        |       |                                       |
| Window winder RR             | <i>v</i> |       |                                       |
| Rear view mirrors            | ~        |       |                                       |
| Radio (basic test only)      | ~        |       |                                       |
| CD (basic test only)         | ~        |       |                                       |
| Number of keys               | 1        |       |                                       |
| Central locking              | 1        |       |                                       |
| Remote locking               |          |       | - V                                   |
|                              |          |       | .,                                    |
| Sat. Nav. (basic test only)  | 1        |       | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |

| inspected by: John Linusay |
|----------------------------|
|----------------------------|

19 Nov 2018

~

Reversing camera