

Report ID: 18,638,244 Version: 5 16 Jan 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2003	<b>Registration:</b>	JCA368	<b>Reg Expiry:</b>	13 Mar 2019	Engine			
WoF Expiry:	03 Oct 2019	Odometer:	170,539 Kms	Good No:	18638244	Oil level	~		
VIN:	6G1YK54F03L972947	Next Service:	180547	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	SC S P	-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S D C SC S D S D						Operation	on 🖌		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					741L	CV joints			~
* = decals	S PT SC 916			- NL	ELL SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P SC W S S P W						Performance	~		
Dedulae		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	d depth	of tyre	es)
Fine chips on screen. L/H wing mirror casing broken									mm
	-					Right front	2.		mm
						Left rear	3.		mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine cov	er missing .					Suspension performance	~		
	J					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	hole on dr	ivers side .				Head lights	~		
50005						Tail lights	~		
Carpets	Average					Indicators	~		$\left  - \right $
Panels	Average					Dashboard warning lights	~		+
						Wipers (front & rear)	~		$\left  - \right $
Dashboa	rd Average					Window winder FL	~		++
						Window winder FR	~		$\left  - \right $
General Comments						Window winder RL	~		$\left  - \right $
Nice V8 Commodore sedan.						Window winder RR	~		+
						Rear view mirrors	~		$\left  \right $
						Radio (basic test only)	~		+
						CD (basic test only)	~		$\left  - \right $
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			
Koad Con	attions During Tes	u Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			
									~
Inspected by: Daryll Timms Date: 21 Nov 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....