

Report ID: 18,638,325 Version: 2 02 Dec 2018 Created:

Make:	BMW	Model:	1301	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006		HGF982	Reg Expiry:	27 Jul 2019	Engine			L
WoF Expiry:		Odometer:	117,073 Kms	Good No:	18638325	Oil level	~		
VIN:	WBAUF92020PS90182	Next Service:		Service Histor	V: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	S	-0	LIS		s	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust						Transmission			
						Operation Noise	ン ン		
PT = paint defe C = crack	ect M			+		Clutch	V		
P = pin dent	Ho								~
* = decals	s pp				Ell'As	CV joints	•		
SC = stone chips						Wheel bearings	 ✓ 		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	.0	mm
						Right front	6.	.0	mm
						Left rear	2.	.0	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							<		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	•					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
Numbe							2		
Road Conditions During Test Drive: Dry Central locking									
			ЛУ			Remote locking	ン ン		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							-		~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: Jeff Luke Date: 20 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: