

Report ID: 18,639,753 Version: 4 28 Jan 2019 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	GBW883	Reg Expiry:	19 Sep 2019	Engine	I	1	L
WoF Expiry:	26 Jan 2020	Odometer:	139,670 Kms	Good No:	18639753	Oil level	~		
VIN:	7AT0C139X11401231	Next Service:	149600	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
					C D W	Performance	~		
Key:	s sc w	-0	SPW SDW	$- \square$	S P W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S D PT SC			715	SCW	Operation	~		
PT = paint def		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					PT SC	Clutch			~
P = pin dent	HIG				74114	CV joints	~		
* = decals	DPTSC 916			-No-	BID SDP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	s SC W		SPW SW		S P W	Performance	~		
Dedulaes		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread		of tyre	es)
Fine chips on screen. R/H wing mirror casing broken.					Left front 2.0 mm				
Jack missing.						Right front		.0	mm
Untidy bod	у.					Left rear		.0	mm
Conditions During Body Inspection: Dry					Right rear			mm	
Conditions During Body Inspection: Dry					Spare				
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Dirty .	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats	Poor					Head lights	~		
						Tail lights	~		
Carpets	Poor					Indicators	~		
Panels	tail light co	overs missing off	hatch door .			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
OK, but untidy.					Window winder RR	~			
Factory rad	io not working, JVC ster	eo wired into glo	ove box			Rear view mirrors	~		
						Radio (basic test only)	-	~	
						CD (basic test only)		~	
						Number of keys	1	-	L
Road Conditions During Test Drive: Dry						Central locking	· ·		
	uning res		Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
	•		••						•
Inspected by: Daryll Timms Date: 21 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: