

Basic Vehicle Condition Guide

Report ID: 18,640,348

Pass

1

~

/

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

15 Apr 2019 Created:

Fail

N/A

1

mm

mm

mm

 mm

7

6

1


Yes

Make: Model: Subaru Exiga **Body Style:** Wagon Year: 2010 Registration: **Reg Expiry:**

Odometer: WoF Expiry: 20 Nov 2019 123,995 Kms **Good No:** 18640348 VIN: 7AT0GF1RX18010615 **Next Service:** 133,960 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil level over full.

Interior Comm	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Air Conditioning / Heater			
Operation	~		
Electrical / Accessories	•		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)		~	
Reversing camera			~
Date: 15 Apr 201	19		
C:			

I have read and	understood this	condition guide.

Donovan Matara

Vame [.]	