


| | | | | | |
|--------------------|------------------|----------------------|-------------|-------------------------|-------------|
| Make: | Ford | Model: | Territory | Body Style: | SUV |
| Year: | 2005 | Registration: | CYF474 | Reg Expiry: | 11 Feb 2019 |
| WoF Expiry: | 07 Mar 2019 | Odometer: | 269,826 Kms | Good No: | 18833375 |
| VIN: | 6FPAAJGAT5G91047 | Next Service: | | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs


Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Roof lining sagging, Dashboard tray lid not closing
Tailgate outer trim broken, insecure. Water inside LH tail lamp
All tyre worn out, FR tyre inner wear
FL power window not working
Mirror switch insecure

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

RL CV boot leak
Bonnet gas strut weak
Engine oil leak
Power steering fluid leak
Battery insecure

Interior Comments

| | |
|-----------|-------------|
| Seats | Poor |
| Carpets | Poor |
| Panels | Poor |
| Dashboard | Screw holes |

General Comments

Ignition key excess play
ESP light stays on

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 0 | mm | |
| Right front | 0 | mm | |
| Left rear | 0 | mm | |
| Right rear | 0 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | | ✓ | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | | ✓ | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Mathew Varghese

Date: 04 Dec 2018

I have read and understood this condition guide.

Name:

Signature: