

Basic Vehicle Condition Guide

Report ID: 18,833,415


Version: 1

Created: 28 Nov 2018

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2007 Registration: LHT95 Reg Expiry: 02 Dec 2018 WoF Expiry: **Odometer:** 20 Apr 2019 97,883 Kms **Good No:** 18833415 VIN: 7AT0C13JX18309560 Next Service: 103351 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Minor stone chips front screen. Bootlid release not working. Right parklight not working.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Brian Hill Date: 28 Nov 2018

Name:

| | Pass | Fail | N/A |
|--|-----------------------|------|----------|
| Engine | | | 1 |
| Oil level | - | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | - | | |
| Cooling System | | | 1 |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | | | |
| Transmission | | | _ |
| Operation | • | | |
| Noise | - | | |
| Clutch | | | V |
| CV joints | ~ | | |
| Wheel bearings | ' | | |
| Brakes | | | |
| Performance | - | | |
| Hand Brake | | | |
| Tyres (lowest observed tread | | | |
| Left front | | 4 | mm |
| Right front | 3 | | mm |
| Left rear | 3 | | mm |
| Right rear | | 4 | mm |
| Spare | | Yes | |
| Suspension | | | 1 |
| Suspension performance | - | | |
| Steering performance | - | | |
| Shock absorbers Air Conditioning / Heater | <i>-</i> | | |
| | | | |
| Operation Electrical / Accessories | | | |
| Head lights | | | |
| Tail lights | • | | |
| Indicators | 1/ | | |
| Dashboard warning lights | • | | |
| Wipers (front & rear) | 1/ | | |
| Window winder FL | V V V V V | | |
| Window winder FR | 1/ | | |
| Window winder RL | • | | |
| Window winder RR | 1/ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | V | | |
| CD (basic test only) | V | | |
| Number of keys | 1 | | |
| Central locking | ' ' | | |
| Remote locking | <i>v</i> | | |
| Sat. Nav. (basic test only) | | | 1 |
| Reversing camera | | | V |
| eversing curriera | | | |

Signature: