

Basic Vehicle Condition Guide

Report ID: 18,833,766

Pass

Version: 3

Engine

Created: 27 Nov 2018


Fail

N/A

Make: Model: Mitsubishi Pajero **Body Style:** Wagon Year: 2001 Registration: GEM242 Reg Expiry: 20 Mar 2019 **Odometer:** WoF Expiry: 09 Apr 2019 142,698 Kms **Good No:** 18833766 VIN: 7AT0CJ08X11200779 Next Service: 152000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

 $Both\ head light\ lens\ dirty. Rust\ left\ front\ gaurd. Surface\ rust\ spot\ on\ roof.\ Surface\ rust\ back\ door.$

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Surface rust under carriage. Sign of fluid leak rear shocks. Surface rust rear suspension. Both front brake rottors groved.

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Surface rust tailgate door frame.AC not cold.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Oil level	<i>-</i>		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	2S)
Left front		8	mm
Right front	8		mm
Left rear	7		mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat Nay (basic test only)			1

I have read and understood this condition guide.

Eddie Marsters

Name [,]			

27 Nov 2018

1

Reversing camera