

Basic Vehicle Condition Guide

Report ID: 18,833,922


Version: 2

Created: 01 Dec 2018

Make: Model: Toyota Corolla **Body Style:** Wagon Year: 2001 Registration: FLW2 Reg Expiry: 21 Jan 2019 WoF Expiry: **Odometer: Good No:** 01 Dec 2019 175,735 Kms 18833922 VIN: 7AT0H607X10104821 Next Service: 185000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 30 Nov 2018

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
d depth	of tyre	es)
3	.5	mm
4.9		mm
6.4		mm
6.6		mm
Yes		
~		
~		
~		
ı		.1
		Т
V		
'		
<i>v</i>		<u> </u>
<i>y y</i>		
<i>y y</i>		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
V V V V V V V		
V V V V V V V		
V V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V V		
V V V V V V V		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature: