

Report ID: 18,834,356 Version: 3 15 Feb 2019 Created:

Make:	Mitsubishi	Model:	Colt	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	HZH900	Reg Expiry:	01 Mar 2019	Engine			L
	28 Mar 2019	Odometer:	119,392 Kms	Good No:	18834356	Oil level	~		
VIN:	7AT0CJ0XX14304587	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for any and milages	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SP W	-0	SP P	-	s	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc w			210	HIL SW	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack					R PT SC	Clutch			~
P = pin dent	HIG				74 <u>11</u> 4	CV joints	~		
*= decals SC 919 S						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	D SC W W		S D S D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Aerial wand missing						Tyres (lowest observed tread depth of tyres)			
						Left front	5 mm		
						Right front	5	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody	oxidisation					Suspension performance	~		
						Steering performance	~		
Shock absorbers						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Stains on s	seats				Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 15 Feb 2019									

Name: