

Report ID: 18,834,506 Version: 1 30 Nov 2018 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2002	Registration:		Reg Expiry:	14 Jan 2019	Engine	1 435	1 dii	
WoF Expiry:		Odometer:	196,510 Kms	Good No:	18834506	Oil level		~	
VIN:	7AT0GF0BX10017713			Service Histor		Smoke & fumes		V	
	7A10GF06A10017713	Next Service.	II/d	Service mistor	• NO	·	~		
	port is not a warranty					Performance	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Noise 🖌			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:			SC S		SC	Performance	~		
S = scratch	~	\sim (O)		5(O)-	\checkmark	Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	sscw 96				HILLING	Operation	~		
PT = paint defe	ect NM	1				Noise	~		
C = crack				\square	SC	Clutch			~
P = pin dent	sc de				74HL	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	w	e	SC		D	Performance	~		
 Body Insr	pection Comments	Note: som	e defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Right side wind deflector broken						Tyres (lowest observed tread depth of tyres)			
						Left front	5	.9	mm
						Right front		.9	mm
						Left rear		.1	mm
Conditions During Rody Inspections						Right rear	3		mm
Conditions During Body Inspection: Dry						Spare		.J Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Brake rotors warn pads low					Suspension performance	~			
Large engine oil leak						Steering performance	~		
Left rear tyr	e inside wall cut					Shock absorbers	~		
							V		
						Air Conditioning / Heater			1
Interior Comments						Operation			
	Good					Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	ور مراجع المراجع الم	doorpanel	long broken			Indicators	~		
Panels	right front	door panel light	IEIIS DIOKEN			Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
			,			Remote locking		~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ian Dunn Date: 27 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: