

Basic Vehicle Condition Guide

Report ID: 18,835,065


Version: 3

Created: 07 Jan 2019

Make: Model: Holden Vectra **Body Style:** Sedan Year: 2004 Registration: CFQ623 Reg Expiry: 06 Jul 2019 WoF Expiry: **Odometer:** 21 Dec 2019 112,721 Kms **Good No:** 18835065 VIN: W0L0ZCF6941055898 Next Service: 121,000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Law Date: 08 Dec 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	5.0		mm
Left rear	3.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

Signature: