

Report ID: 18,836,084 Version: 2 21 Feb 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2005	Registration:	CQJ802	Reg Expiry:	03 Jun 2019	Engine			
WoF Expiry:	26 Nov 2019	Odometer:	105,865 Kms	Good No:	18836084	Oil level	~		
VIN:	JN1CNUD22A0049263	Next Service:	115410	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and ti	lis can be analiged ic		inarge.	Coolant condition	~		
	S		S SD		S D	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	s AR			10		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	s de				~HHL	CV joints	~		
* = decals		10		10	ED SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S D	\sim	S S			Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.0	mm
						Right front	6.0		mm
						Left rear	6.0		mm
Conditions During Body Inspection: Dry						Right rear	6.0		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
minor Brake	e vibration					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights		~	
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		
General Comments Battery light sometimes on dash					Window winder RL	~			
	Contentities off udsh					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
	ning Machaniara	Timeire	<u>Chain</u>			Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			2
Inspected by: Dion Mair Date: 21 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: