

Report ID: 18,837,540 Version: 1 05 Dec 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Wagon		Pass	Fail	N/A
Year:	1999	Registration:	LRB745	Reg Expiry:	21 Jul 2019	Engine			L
WoF Expiry:	14 Mar 2019	Odometer:	317,999 Kms	Good No:	18837540	Oil level	~		
VIN:	6H8VTL35HXL493303	Next Service:	325000	Service Histor	y: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	oration is made	for and milago	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	P SC	-0	SRP SP	-161-	SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	E S	Operation	~		
R = rust PT = paint def				r In		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HC					CV joints			~
* = decals	PT SC 916				EIIP I	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SP						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
	pection Comments							oftyre))
RH taillight lens cracked. No center caps on wheels. Clearcoat is coming off vehicle. Corrosion on wiper arms. Rust on inside of RF door.						Tyres (lowest observed tread depth of tyres) Left front 4			-
Rust on Inside of RF door. Roof lining coming off. LR and RF speaker covers damaged. Wear on seats. Damage on keys.							1	mm	
						Right front Left rear		1	mm
								5	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Engine has oil seepage. Front brake pads low.						Suspension		-	
Engine has	oli seepage. Front brak	e pads low.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Poor						Electrical / Accessories			
Seats	1001					Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Excess vibration from engine, possibly engine mount.					Window winder RR	~			
Drives ok.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 05 Dec 2018									

I have read and understood this condition guide.

Name:

Signature: